

25

Government of Bihar
Public Health Engineering Department
 Water Quality Testing Report
 Sample Given By :- Uday Sankar Pr Singh

District Name: Purnea

Division Name: P.H. Division, Purnea

Month:- May-2026

District Name: Punea			Division Name: P. n. Division, Punea													Remarks	
Sl. No.	Block	Panchyat	Village/Habitation	Location of source	Type of source	Parameters											Total Coll
						pH	Turb.	EC	TDS	TH	Cl	Alka.	Fe	Ca	Mg		
1	K. Nagar	Ganeshpur	Porora W. No-10	Mount Carmel English School	T.W	7	2.0	460	230	176.4	40.52	196	0.382	47.04	14.28	Negative	जल नमूना का संग्रह स्वयं लम्बरिया के द्वारा किया गया है। जल शुद्धता की गारंटी जल संग्रह करने के तरीके एवं संग्रहकर्ता के उपर निर्भर करता है।
BIS:10500:2012(Second Revision)						Desirable Limit*										Negative	
						6.5-8.5	5.0	-	500	200	250	200	1.0	75	30		
						Permissible Limit* in absence of alternate source										Negative	
						NR	10.0	-	2000	600	1000	600	N.R	200.0	100.0		

P.H. Division, Purnea

Chemist

P.H. Sub Division, Purnea

A.E.

Executive Engineer
 P.H. Division, Purnea
 Executive Engineer
 P.H. Division, Purnea

MANAGER
 Mount Carmel English School
 Parora, Purnea

PRINCIPAL
 Mount Carmel English School
 Parora, Purnea